

WATER WELL REPORT

Application No.

STATE OF WASHINGTON

Permit No.

Mail: 42 W. Crescent Harbor Oak Harbor, 98277

(1) OWNER: Name Ron Hanson

Address

(2) LOCATION OF WELL: County Island

1/4 SW 1/4 Sec 33 T. 33 N. R. 1 E W.M.

Bearing and distance from section or subdivision corner

(3) PROPOSED USE: Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one) _____
New well ☒ Method: Dug ☐ Bored ☐
Deepened ☐ Cable ☐ Driven ☐
Reconditioned ☐ Rotary ☒ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 107 ft. Depth of completed well 107 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: 6" Diam. from 0 ft. to 102 ft.
Threaded ☐ " Diam. from _____ ft. to _____ ft.
Welded ☐ " Diam. from _____ ft. to _____ ft.

Perforations: Yes ☐ No ☒
Type of perforator used _____
SIZE of perforations _____ in. by _____ in.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes ☒ No ☐
Manufacturer's Name UOP JOHNSON
Type 5' STAINLESS STEEL Model No. _____
Diam. 6" Slot size 8 from 102 ft. to 107 ft.
Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes ☐ No ☒ Size of gravel: _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.
Material used in seal Cement
Did any strata contain unusable water? Yes ☐ No ☒
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____
Type: _____ H.P. _____

(8) WATER LEVELS: Land-surface elevation _____ ft.
Static level 73 ft. below top of well Date 6-14-79
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? Yes ☐ No ☒ If yes, by whom? _____
Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.

" " " " " "
" " " " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test _____
Bailer test 20 gal./min. with 30 ft. drawdown after _____ hrs.
Artesian flow _____ g.p.m. Date 6-14-79
Temperature of water _____ Was a chemical analysis made? Yes ☐ No ☒

(10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
Sand	0	25
Brown clay clay	25	50
Sand	50	90
Water and sand	90	107

NOV 1 1979
DEPT. OF ECOLOGY

Work started June 13, 1979 Completed June 14, 1979

WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME DAHLMAN PUMP AND DRILLING
(Person, firm, or corporation) (Type or print)

Address P.O. Box 422 Burlington, 98233

[Signed] R. C. Johnson
(Well Driller)

License No. 0222 Date June 22, 1979